

## سوال نمبر 1793

منجانب : شاہ فیصل خان ایم۔ پی۔ اے صوبائی اسمبلی صوبہ خیبر پختونخوا

نمبر شمار	سوال	جواب
	کیا وزیر مواصلات و تعمیرات ارشاد فرمائیں گے کہ۔	
(الف)	آیا یہ درست ہے کہ سال 2013 سے 2018 تک ہنگوٹل میں مین سڑک اور ہنگو بائی پاس روڈ کی مرمت کیلئے حکومت نے کے پی ایچ اے کو فنڈ فراہم کیا ہے۔	جی ہاں۔
(ب)	اگر الف کا جواب اثبات میں ہو تو مذکورہ فنڈ کہاں کہاں خرچ کیا گیا ہے اور اس فنڈ سے ان سڑکوں کا مرمت کا کام کہاں کہاں کیا گیا۔ تفصیل فراہم کی جائے۔	مقررہ فنڈ جو 2013 سے 2018 تک ہنگوٹل میں روڈ اور ہنگو بائی پاس پر خرچ کیا گیا ہے۔ اُسکی سال بہ سال تفصیل لف ہیں۔

**Package # 19/2013-14 : S/R AOM&R to Provincial Highway S-7 Hangu -**

**Doaba road.**

S.No	Scope of Work	Starting RD	End RD	Remarks
1	Bitumenous Tack Coat	KM 40 39+475 KM 42 41+000	KM 40 40+750 KM 42 41+100	Hangu Bazzar near Hangu CNG
2	Water Bound Macadam	KM 42 41+525	KM 42 41+620	near Masjid Haleema
3	Prime Coat	KM 42 41+525	KM 42 41+620	near Masjid Haleema
4	Asphalt Wearing Course	KM 40 39+475 KM 42 41+000	KM 40 40+750 KM 42 41+100	Hangu Bazzar near Hangu CNG
5	Retaining Walls	Km 46 L/S 45+000	Km 46 L/S 45+150	near Uni; Campus
6	Structural Backfill	Km 46 L/S 45+000	Km 46 L/S 45+150	near Uni; Campus
7	Formation of Shoulders	Km 43+000	Km 47+800	Bagatu check post Qazi Pump
8	Double Bitumenous Surface Treatment	Km 53+200	Km 56+238	Togh sarai

**Package # 20/2014-15 : S/R AOM&R to Provincial Highway S-7 Hangu -**

**Doaba road.**

S.No	Scope of Work	Starting RD	End RD	Remarks
1	Double Bitumenous Surface Treatment	44+800 45+000 45+450 48+500 51+400 67+525 68+200 68+900 69+000 69+400 70+200	45+000 45+250 46+000 49+000 51+683 67+850 68+275 69+000 69+120 69+500 70+240	Near Qazi Pump Near Qazi Pump Near Qazi Pump Kotki Toghsarai Toghsarai Sarkai Sarkai Sarojai Sarkai Sarkai
2	36" Dia Pipe culvert	68+200 68+600 68+800		Sarojai Sarkai
3	27" Dia Pipe Culvert	49+700		Kokti
4	36" Dia Pipe Culvert	57+800		M.Khwaja (Diversion)
5	Grooving	65+000	65+650	Azeemi bamda

6	Embankment for diversion & TST reaches	km 69 km 58 km 70		Sarozai M.Khwaja (Diversion) Sarozai
7	Retaining Walls	km 98		Restoration of Flood damages to Tor Bridge
8	Structural Backfull	km 98		Restoration of Flood damages to Tor Bridge
9	Sub Base	68+200 43+100	68+350 43+300	Sarozai Tableghi markaz
10	Water Bound Macadam	65+000 68+200 43+100	65+550 68+400 43+300	Azeemi Banda Sarozai Tableghi markaz
11	T.S.T	65+000 69+200 69+550	65+575 69+550 69+900	Azeemi Banda Sarozai Sarozai
12	Drain	42 L/S 60 L/S 60 R/S 61 L/S		50 meters Sherawi 75 meters Kahi 50 meters Kahi 50 meters Kahi
13	RCC Culvert Slab	57+800		M.Khwaja damaged Culvert Slab restoration

**Package # 21/2015-16 : S/R AOM&R to Provincial Highway S-7 Hangu -  
Doaba road.**

S.No	Scope of Work	Starting RD	End RD	Remarks
1	Double Bitumenous Surface Treatment	57+325 58+000 59+200	58+000 58+765 59+470	Kahi Kahi Kahi
2	Bridge Extansion Joint	94+800		16.80 meter Thall Bridge

**Package # 11/2016-17 : S/R AOM&R to Provincial Highway S-7 Hangu -**

**Doaba road.**

S.No	Scope of Work	Starting RD	End RD	Remarks
1	Double Bitumenous Surface Treatment	48+600	48+900	Kotki
		48+950	49+000	Kotki
		49+000	49+100	Kotki
		49+250	49+500	Kotki
		50+650	50+950	Kotki
		67+275	67+525	Sarozai
		69+500	70+000	Sarozai
		70+000	70+200	Sarozai

**Package # 34/2017-18 : S/R AOM&R to Provincial Highway S-7 Hangu -**

**Doaba road.**

S.No	Scope of Work	Starting RD	End RD	Remarks
1	Grooving	44+200		Bagatu Check post
		56+725		M.Khwaja
2	Retaining walls / Protection wall	85+500 (L/S)		Mamu Khwar
		87+900 (L/S)		Thall Cantt
		89+800 (R/S)		Thall Cantt
3	Water Bound Macadam	<b>Hangu bypass :</b>		
		0+300		150 meters
		1+200		286 meters
		2+750		283 meters
		5+200		233 meters
		<b>Hangu - Doaba</b>		
44+200		206 meters Bagatu C.P		
56+725		281 meters M.Khwaja		
4	P.C.C (1:2:4)	85+500		Bridge Pile Protection
		56+725		M. Khwaja
5	T.S.T	56+725		M.Khwaja