


سوال نمبر ۱۵۶۰۳

منجانب : جناب عنایت اللہ صاحب رکن، صوبائی اسمبلی صوبہ خیبر پختونخوا

سوال	جواب	ر شمار
کیا وزیر مواصلات و تعمیرات ارشاد فرمائیں گے کہ۔		
(ف) آیا یہ درست ہے کہ محکمہ کے زیر نگرانی پشاور ڈویژن میں شامل اضلاع کے دفاتر میں ناکارہ اور ناقابل استعمال اسکرپٹ سرکاری گاڑیاں، ٹرک، و مشینریاں عرصہ دراز سے موجود ہیں۔	جی ہاں محکمہ کے زیر نگرانی پشاور ڈویژن میں شامل اضلاع کے دفاتر میں ناکارہ خراب اور ناقابل استعمال اسکرپٹ سرکاری گاڑیوں، ٹرک و مشینریاں عرصہ دراز سے کچھ اضلاع میں موجود ہے اور کچھ میں نہیں۔ تفصیل لف ہے۔	
(ب) اگر الف کا جواب اثبات میں ہو تو:- i) پشاور ڈویژن میں شامل اضلاع کے نام اور ان دفاتر میں ناکارہ خراب اور ناقابل استعمال اسکرپٹ سرکاری گاڑیاں، ٹرک مشینری کی تفصیل فراہم کی جائے۔ ii) مذکورہ گاڑیاں و مشینری کب سے پڑی ہے نیز خرابی نوعیت و مرمت کی لاگت کی تفصیل فراہم کی جائے۔ مذکورہ اسکرپٹ، گاڑیوں اور مشینری کی نیلامی کے لیے کیا اقدامات کیے گئے ہیں۔ تفصیل فراہم کی جائے۔	اس سلسلہ میں حال ہی میں چیف سیکرٹری صاحب کے احکامات صادر ہوئے ہیں۔ جن کی روشنی میں تمام ناکارہ گاڑیوں اور مشینری/پلانٹ کی نیلامی قوانین کے مطابق اگلے چند ماہ میں کر دی جائے گی۔	

**DETAIL OF ROAD MAKING MACHINERY (UN-SERVICEABLE) WITH THE OFFICE OF
EXECUTIVE ENGINEER C&W HIGHWAY DIVISION NO-I PESHAWAR**

Sl. No.	Name of Machinery	Location	Total No.	Status		Remarks
				Serviceable	Un-Serviceable	
1.	Master Paver AV Bedford	Aza Khel	2	-	2	Un-Serviceable
2.	Bitumen Distributer	Aza Khel	1	-	1	Un-Serviceable
3.	SV 91 Road Roller	Aza Khel	1	-	1	Un-Serviceable
4.	Chain Dozer	Aza Khel	1	-	1	Un-Serviceable
5.	Burlet Traila	Aza Khel	1	-	1	Un-Serviceable
6.	Motor Grader	Aza Khel	1	-	1	Un-Serviceable
7.	Chips Spreader	Aza Khel	1	-	1	Un-Serviceable
8.	Pay Dozer Purkawa	Aza Khel	1	-	1	Un-Serviceable
9.	Road Roller AV Bedford	Aza Khel	2	-	2	Un-Serviceable
10.	Asphalt Plant	Aza Khel	1	-	1	Un-Serviceable
11.	Paver Finisher	Aza Khel	2	-	2	Un-Serviceable
12.	Generator 250-KVA	Aza Khel	3	-	3	Un-Serviceable
13.	Generator 25-KVA	Aza Khel	3	-	3	Un-Serviceable
14.	Compressor	Aza Khel	1	-	1	Un-Serviceable
15.	JCB Front End Loader	Aza Khel	2	-	2	Un-Serviceable
16.	Front End Loader International	Aza Khel	2	-	2	Un-Serviceable
17.	Dumper Truck	Aza Khel	7	-	7	Un-Serviceable
18.	Heavy Crian	Aza Khel	1	-	1	Un-Serviceable
19.	Rotery Broom	Aza Khel	1	-	1	Un-Serviceable
20.	Tendum Road Roller	Aza Khel	1	-	1	Un-Serviceable
21.	Penumatic Tyre Roller	Aza Khel	2	-	2	Un-Serviceable
22.	Roller SV 91	Aza Khel	3	-	3	Un-Serviceable


 EXECUTIVE ENGINEER
 HIGHWAY DIVISION
 PESHAWAR



No. C&W/10/1563

Dated 27/06/2016

To

The Executive Engineer,
C&W Highway Division Peshawar.

Subject: AUCTION OF MACHINERY OF HIGHWAY DIVISION PESHAWAR AT AZA KHEL.

Reference: 1. S.E. C&W Circle Peshawar letter No. 1324/24-SE dated 23-05-2016.
2. S.E. C&W Circle Peshawar letter No. 1680/24-SE dated 22-06-2016.

As recommended by the auction committee and forwarded by Superintending Engineer, C&W Circle Peshawar vide letter quoted under reference on the subject cited above, the rates of the followings auctioneers noted against each are hereby approved under S.N 10 "Power to dispose surplus or un-serviceable motor vehicles, machinery, equipment, spares, stores by auction after due publicity", Third Schedule, Powers common to all departments, Delegation of Powers under Financial Rules and Powers of Re-appropriation Rules 2001, subject to fulfillment of all codal formalities and financial regularities.

Lot No.1			
S.No	Name of Machine	Name of Bidders	Offered Bid
1.	Static Road Roller Shahzore	Muhammad Sharif	Rs 1710000/-
2.	Static Road Roller Shahzore		
3.	Static Road Roller China		
10	Fedroma Roller		
Lot No.2			
S.No	Name of Machine	Name of Bidders	Offered Bid
8	Zettlemayre Tendeum	Akhtar Munir	1700000/-
9	Zettlemayre Tendeum		
11	AV Badford Roller		
12	AV Badford Roller		
Lot No.3			
S.No	Name of Machine	Name of Bidders	Offered Bid
14	Vibratory Road Roller SV-91	Akhtar Munir	2500000/-
15	Vibratory Road Roller SV-91		
16	Vibratory Road Roller SV-91		

Auction Register (in original) alongwith auction documents are returned herewith for record in your office. Depute an official to collect the Auction Register and relevant documents from this office within 03 days positively.

Encl: As above

c.c.

1. Superintending Engineer, C&W Circle Peshawar for information.
2. Deputy Secretary (Admn) C&WD Khyber Pakhtunkhwa Peshawar.

CHIEF ENGINEER (CENTRE)

CHIEF ENGINEER (CENTRE)

S. No	Nomenclature of Machinery			Condition	Detail of repairs along with repair cost		Capital Cost in Million	Present Location
	Type	Make	Model		Detail of repairs	Est/ Cost		
1	2	3	4	5	6	7		
1	Motor Grader	Champion	1995	Repairable	Engin Over hauling, Tyres, Electric pannel needed.	1.00 M	3.700	PKHA Machinery Yard Shah Alam out of order)
2	Motor Grader	Champion	1995	Repairable	Engin Over hauling, Tyres, Electric pa nnel needed.	1.00 M	3.700	PKHA Machinery Yard Shah Alam out of order)
3	Motor Grader	Champion	1997	Repairable	Engin Over hauling, Tyres, Electric pannel needed.	1.00 M	3.700	PKHA Machinery Yard Shah Alam out of order)
4	Motor Grader	Champion	1997	Repairable	Engin Over hauling, Tyres, Electric pannel needed.	1.00 M	3.700	PKHA Machinery Yard Shah Alam out of order)
5	Motor Grader	Champion	1997	Repairable	Engin Over hauling, Tyres, Electric pannel needed.	1.00 M	3.700	PKHA Machinery Yard Shah Alam out of order)
6	Motor Grader	Champion	1997	Repairable	Engin Over hauling, Tyres, Electric pannel needed.	1.00 M	3.700	PKHA Machinery Yard Shah Alam out of order)
7	Vibratory Roller	Ingersoll	1993	Repairable	Engin Over hauling, Tyres, Electric pannel needed.	.800 M	3.300	PKHA Machinery Yard Shah Alam out of order)
8	Vibratory Roller	Ingersoll	1993	Repairable	Needs Hydraulic Pump Repair	0.800 M	3.300	PKHA Machinery Yard Shah Alam out of order)
9	Vibratory Roller	Ingersoll	1993	Repairable	Overhauling, Turbo & batteries needed	0.800 M	3.300	PKHA Machinery Yard Shah Alam out of order)
10	Vibratory Roller	Ingersoll	1993	Repairable	Overhauling, Turbo & batteries needed	0.800 M	3.300	PKHA Machinery Yard Shah Alam out of order)
11	Vibratory Roller	Ingersoll	1993	Repairable	Overhauling, Turbo & batteries needed	0.800 M	3.300	PKHA Machinery Yard Shah Alam out of order)
12	Vibratory Roller	Ingersoll	1993	Repairable	Overhauling, Turbo & batteries needed	0.800 M	3.300	PKHA Machinery Yard Shah Alam out of order)
13	Vibratory Roller	Ingersoll	1993	Repairable	Overhauling, Turbo & batteries needed	0.800 M	3.300	PKHA Machinery Yard Shah Alam out of order)
14	Vibratory Roller	Ingersoll	1993	Repairable	Overhauling, Turbo & batteries needed	0.800 M	3.300	PKHA Machinery Yard Shah Alam out of order)
15	Vibratory Roller	SV - 91	1985	Irrepairable	Irrepairable		1.125	Mechanical work Shop Peshawar (OFFERED FOR AUCTION)
16	Static Roller	China	1993	Repairable	Overhauling & batteries needed	0.500 M	0.700	PKHA Machinery Yard Shah Alam out of order)
17	Static Roller	China	1993	Repairable	Overhauling & batteries needed	0.500 M	0.700	PKHA Machinery Yard Shah Alam out of order)
18	Static Roller	China	1993	Repairable	Overhauling & batteries needed	0.500 M	0.700	PKHA Machinery Yard Shah Alam out of order)
19	Static Roller	China	1993	Repairable	Engine Overhauling needed	0.500 M	0.700	PKHA Machinery Yard Shah Alam out of order)
20	Static Roller	China	1993	Repairable	Engine Overhauling needed	0.500 M	0.700	PKHA Machinery Yard Shah Alam out of order)
21	Static Roller	China	1993	Repairable	Engine Overhauling needed	0.500 M	0.700	PKHA Machinery Yard Shah Alam out of order)
22	Static Roller	China	1993	Repairable	Engine Overhauling needed	0.500 M	0.700	PKHA Machinery Yard Shah Alam out of order)
23	Static Roller	China	1993	Repairable	Engine Overhauling needed	0.500 M	0.700	PKHA Machinery Yard Shah Alam out of order)
24	Static Roller	China	1993	Repairable	Engine Overhauling needed	0.500 M	0.700	PKHA Machinery Yard Shah Alam out of order)
25	Static Roller	China	1994	Repairable	Engine Overhauling needed	0.500 M	0.700	PKHA Machinery Yard Shah Alam out of order)
26	Static Roller	China	1993	Repairable	Engine Overhauling needed	0.500 M	0.700	PKHA Machinery Yard Shah Alam out of order)
27	Bitumen Distributor	Japan	1996	Repairable	Engine Overhauling needed	0.500 M	2.000	PKHA Machinery Yard Shah Alam out of order)
28	Dumper Truck	Nissan	1996	Repairable	Needs major repair	0.500 M	1.500	PKHA Machinery Yard Shah Alam out of order)

SUB Engineer Incharge
PKHA Peshawar

Assistant Director (MA)
PKHA Peshawar